



Import Specialties of Columbia, LLC.
2100 Rosewood Drive
Columbia, SC 29205
803-799-2686

Invoice# 10844 Order ID: 18623 1/24/2023 Service Writer: KD Page 1

Gregory James
418 Jordan Way
Lexington, SC 29022

Tag: THV 169
Make: 1967 Jaguar 340
VIN: P1J80132DN
Mileage: In- 0 Out- 1

Customer States: Sputters when driving Fuel is old, non-ethanol and fuel treatment has always been used Check oil/fluids Brakes squeal	\$0.00
Customer States: Total	\$0.00

Inspection	Inspect steering, suspension, exhaust, and cooling systems. Check brakes at all four wheels. Inspect tires and check tire pressures. Inspect all belts, hoses, and fluid levels. Check battery, starting and charging systems. road test vehicle. Check for dash light and pull reading if needed.	\$264.00
Tech - EB	Inspection Total	\$264.00

Steering-Tie Rod	Remove and replace tie rod ends. right tie rod end bent	\$132.00
Parts:	1 C22678 Inner tie rod end n/c	
	1 C22678 Right tie rod end \$172.80	\$172.80
Tech - EB	Steering-Tie Rod Total	\$304.80

Engine-Plug&wire	Repair or Replace Spark Plugs and/or Wires.	\$396.00
Parts:	6 EAC8916 Spark Plug \$87.36	
	1 SBS1010 Plug Lead kit \$209.65	
	1 C30121 Lead Terminal \$16.51	
	7 C28854 Lead Sleeve \$52.64	\$366.16
Tech - EB	Engine-Plug&wire Total	\$762.16

Fuel-CarbRepair	Repair carburetor as needed. Rebuild or replace if necessary. Check emissions and set as specified.	\$1,320.00
Parts:	2 CSK37 Carb Service Kit \$428.24	
	1 C16484 Air filter \$66.82	\$495.06
Sublet:	Freight \$15.00	\$15.00
Tech - EB	Fuel-CarbRepair Total	\$1,830.06

Fuel-Filter	Replace fuel filter.	\$52.80
Parts:	1 C28080 Fuel Filter \$18.31	\$18.31
Tech - EB	Fuel-Filter Total	\$71.11

Cooling-Flush	Flush and reverse flush cooling system. Add fresh coolant and test for temperature range and leaks.	\$132.00
Parts:	2 ANTIFREEZE ANTIFREEZE \$29.54	\$29.54

Tech - EB	Cooling-Flush Total	\$161.54
-----------	---------------------	----------

Distributor	Remove and replace Ignition Distributor.		\$224.40
Parts:	1 JLM9523	Distributor cap	\$26.05
	1 JLM9656	Condenser	\$13.46
	1 JLM263U	Rotor Arm	\$23.39
	1 JLM9520	Contact set	\$16.61
Tech - EB	Distributor Total	\$303.91	

Brake-Caliper	Remove and replace Brake Caliper(s) as needed.		\$1,320.00
Parts:	1 PAB-320	Steel line	\$25.21
	2 C13686	Front brake hose	\$62.04
	1 C13687	Rear brake hose	\$31.02
	1 12319	Front caliper seal kit	\$71.98
	1 10821	Brake pad kit	\$113.57
	4 8778G	Rear Brake Caliper Cylinder	\$1,175.92
Tech - EB	Brake-Caliper Total	\$2,799.74	

Brake-Emergency	Check emergency brake for function and repair as needed.		\$132.00
Parts:	1 8522	handbrake pad set	\$60.70
	1 PAB330	Brake Line	\$23.05
	1 PAB340	Brake Line	\$23.05
Tech - EB	Brake-Emergency Total	\$238.80	

Wiper-Diag	Diagnose wiper blade operation and advise.	\$158.40
Tech - EB	Wiper-Diag Total	\$158.40

service-A	Oil Change & visual vehicle inspection which includes inspecting the steering, suspension, exhaust, and cooling systems. Check brakes at all four wheels. Inspect tires and check tire pressures. Inspect all belts, hoses, and fluid levels. Check battery, starting and charging systems. road test vehicle.		\$57.39
Parts:	12 15w40	15W40	\$156.00
	1 R85348	Oil filter	\$14.08
Tech - EB	service-A Total	\$227.47	

Fuel-Tank	Remove fuel tank for inspection or repair.		\$462.00
Parts:	1 C17565U	Fuel Tank	\$1,340.32
Tech - EB	Fuel-Tank Total	\$1,802.32	

Brake-Master	Replace brake master cylinder, fill system with specified DOT fluid and bleed.		\$198.00
Parts:	1 C27160	Brake Master Cylinder	\$154.24
Tech - EB	Brake-Master Total	\$352.24	

DOT 3

Clutch-Slave	Replace clutch slave cylinder, bleed system and adjust for proper free play and release where adjustable.		\$132.00
Parts:	1 C11603	Clutch Hose	\$27.68
	1 C29801	Clutch Slave Cylinder	\$156.57
Tech - EB	Clutch-Slave Total	\$316.25	

Service - Diff	Remove differential cover, drain and fill differential with recommended fluid. Reseal housing.			\$0.00
Parts:	1	3840R	Diff Pinion Seal	\$24.64
	1	607183J	Spacer seal	\$4.33
	2	GEAR OIL	Gear Oil	\$19.86
			Service - Diff Total	\$48.83
Tech - EB				
Wiper Replace	Replace wiper blades			\$26.40
Parts:	2	8183	Blades	\$71.10
			Wiper Replace Total	\$97.50
Tech - EB				
Clutch-Master	Replace clutch master cylinder, bleed system and adjust for proper free play and release where adjustable.			\$330.00
Parts:	1	MHK104	Clutch master cylinder sealkit	\$26.92
	1	28409	3/8 hose	\$45.23
			Clutch-Master Total	\$402.15
Tech - EB				
Engine-Mounts	Replace engine mounts as needed.			\$237.60
Parts:	2	C18556	Engine Mount	\$108.22
			Engine-Mounts Total	\$345.82
Tech - EB				
Body-Mirror	Check and/or replace mirror glass or assembly			\$66.00
			Body-Mirror Total	\$66.00
Tech - EB				
Elec-Lights/Wir2	Elec-Lights/Wires			\$198.00
			Elec-Lights/Wir2 Total	\$198.00
Tech - EB				
Tran-ManualServ	Drain transmission fluid. Fill with specified lubricant(s). Check clutch adjustment and free play and adjust if possible.			\$79.20
Parts:	4	GEAR OIL	Gear Oil	\$35.96
			Tran-ManualServ Total	\$115.16
Tech - EB				
Steer-PowerHose	Replace power steering hose. Fill system with specified fluid. Bleed system and test for leaks.			\$132.00
			Steer-PowerHose Total	\$132.00
Tech - EB				
Elec- Battery	Replace Battery			\$132.00
Parts:	1	24RF3	Battery	\$342.17
			Elec- Battery Total	\$474.17
Tech - EB				
Car Wash	Complementary car wash.			\$0.00
			Car Wash Total	\$0.00

Two years or 24,000 mile warranty on most repairs. We do not use customer supplied parts. Warranty only applicable to vehicles returned to Import Specialties location.

We appreciate your business and referrals. Thank you for choosing Import Specialties of Columbia LLC.

Special ordered parts must be paid for at the time ordered.
No refunds on special ordered parts.

**We are open Monday through Friday
8:00 AM to 5:30 PM.
Please call for an appointment.**

Labor Total	\$6,182.19
Parts Total	\$5,275.24
Sublet Total	\$15.00
Supplies/Waste	\$299.00
Sales Tax	\$445.93
Partial Payments	\$10,000.00
Paid by Amex	\$2,217.36