



Import Specialties of Columbia, LLC.
2100 Rosewood Drive
Columbia, SC 29205
803-799-2686

Work Order Order ID: 18623 12/15/2022 Service Writer: KD Page 1

Gregory James
418 Jordan Way
Lexington, SC 29022

Tag: THV 169
Make: 1967 Jaguar 340
VIN: P1J80132DN

Customer States: Sputters when driving Fuel is old, non-ethanol and fuel treatment has always been used Check oil/fluids Brakes squeal	\$0.00
Customer States: Total	\$0.00

Inspection	Inspect steering, suspension, exhaust, and cooling systems. Check brakes at all four wheels. Inspect tires and check tire pressures. Inspect all belts, hoses, and fluid levels. Check battery, starting and charging systems. road test vehicle. Check for dash light and pull reading if needed.	\$264.00
Inspection Total		\$264.00

Steering-Tie Rod	Remove and replace tie rod ends. right tie rod end bent			\$132.00
Parts:	1 C22678	inner tie rod end	n/c	
	1 c29094	Right tie rod end	\$209.96	\$209.96
Steering-Tie Rod Total				\$341.96

Engine-Plug&wire	Repair or Replace Spark Plugs and/or Wires.			\$396.00
Parts:	6 EAC8916	Spark Plug	\$87.36	
	1 SBS1010	Plug Lead kit	\$209.65	\$297.01
Engine-Plug&wire Total				\$693.01

Fuel-CarbRepair	Repair carburetor as needed. Rebuild or replace if necessary. Check emissions and set as specified.			\$1,320.00
Parts:	2 CSK37	Carb Service Kit	\$428.24	\$428.24
Fuel-CarbRepair Total				\$1,748.24

Fuel-Filter	Replace fuel filter.			\$52.80
Parts:	1 C28080	Fuel Filter	\$18.31	\$18.31
Fuel-Filter Total				\$71.11

Cooling-Flush	Flush and reverse flush cooling system. Add fresh coolant and test for temperature range and leaks.			\$132.00
Parts:	2 ANTIFREEZE	ANTIFREEZE	\$29.54	\$29.54
Cooling-Flush Total				\$161.54

Distributor	Remove and replace Ignition Distributor.			\$224.40
Parts:	1 JLM9523	Distributor cap	\$26.05	
	1 JLM9656	Condenser	\$13.46	
	1 JLM263U	Rotor Arm	\$23.39	

Work Order	Order ID: 18623	12/15/2022	Service Writer: KD	Page 2
1	JLM9520	Contact set	\$16.61	\$79.51
			Distributor Total	\$303.91
Brake-Caliper Remove and replace Brake Caliper(s) as needed.				\$1,320.00
Parts:	1	PAB-320	Steel line	\$14.23
	1	12604	Caliper Kit	\$63.89
	2	C13686	Front brake hose	\$51.82
	1	C13687	Rear brake hose	\$25.91
	1	12319	Front caliper seal kit	\$67.70
	1	10821	Brake pad kit	\$108.18
			Brake-Caliper Total	\$331.73
				\$1,651.73
Brake-Emergency Check emergency brake for function and repair as needed.				\$132.00
			Brake-Emergency Total	\$132.00
Wiper-Diag Diagnose wiper blade operation and advise.				\$158.40
			Wiper-Diag Total	\$158.40
service-A Oil Change & visual vehicle inspection which includes inspecting the steering, suspension, exhaust, and cooling systems. Check brakes at all four wheels. Inspect tires and check tire pressures. Inspect all belts, hoses, and fluid levels. Check battery, starting and charging systems. road test vehicle.				\$57.39
Parts:	12	15w40	15W40	\$156.00
	1	JLM9544	Oil filter	\$16.51
			service-A Total	\$172.51
				\$229.90
Fuel-Tank Remove fuel tank for inspection or repair.				\$462.00
Parts:	1	C17565U	Fuel Tank	\$1,340.32
			Fuel-Tank Total	\$1,340.32
				\$1,802.32
Brake-Master Replace brake master cylinder, fill system with specified DOT fluid and bleed.				\$198.00
Parts:	1	G27160	Brake master cylinder	\$154.24
			Brake-Master Total	\$154.24
				\$352.24
Clutch-Slave Replace clutch slave cylinder, bleed system and adjust for proper free play and release where adjustable.				\$132.00
Parts:	1	C11603	Clutch slave Cylinder	\$156.57
	1	C29801	Clutch hose	\$27.68
			Clutch-Slave Total	\$184.25
				\$316.25
Service - Diff Remove differential cover, drain and fill differential with recommended fluid. Reseal housing.				\$0.00
Parts:	1	3840R	Diff Pinion Seal	\$24.64
	1	607183J	Spacer seal	\$4.33
	2	GEAR OIL	Gear Oil	\$19.86
			Service - Diff Total	\$48.83
				\$48.83
Wiper Replace Replace wiper blades				\$26.40
Parts:	2	8183	Blades	\$71.10
				\$71.10

Wiper Replace Total			\$97.50
Clutch-Master	Replace clutch master cylinder, bleed system and adjust for proper free play and release where adjustable.		\$132.00
Parts:	1 C20526	Clutch master cylinder	\$268.43
		Clutch-Master Total	\$400.43
Engine-Mounts	Replace engine mounts as needed.		\$237.60
Parts:	2 C18556	Engine Mount	\$108.22
		Engine-Mounts Total	\$345.82
Body-Mirror	Check and/or replace mirror glass or assembly		\$66.00
		Body-Mirror Total	\$66.00
Elec-Lights/Wir2	Elec-Lights/Wires		\$198.00
		Elec-Lights/Wir2 Total	\$198.00
Tran-ManualServ	Drain transmission fluid. Fill with specified lubricant(s). Check clutch adjustment and free play and adjust if possible.		\$79.20
Parts:	4 GEAR OIL	Gear Oil	\$35.96
		Tran-ManualServ Total	\$115.16
Steer-PowerHose	Replace power steering hose. Fill system with specified fluid. Bleed system and test for leaks.		\$132.00
		Steer-PowerHose Total	\$132.00

Two years or 24,000 mile warranty on most repairs. We do not use customer supplied parts. Warranty only applicable to vehicles returned to Import Specialties location.

We appreciate your business and referrals. Thank you for choosing Import Specialties of Columbia LLC.

Special ordered parts must be paid for at the time ordered.
No refunds on special ordered parts.

**We are open Monday through Friday
8:00 AM to 5:30 PM.
Please call for an appointment.**

Labor Total	\$5,852.19
Parts Total	\$3,778.16
Sublet Total	\$0.00
Supplies/Waste	\$299.00
Sales Tax	\$326.17
Partial Payments	\$0.00
Total Due	\$10,255.52